

ANNUAL INSPECTION

SAFETY INSPECTION REPORT

For Burnham Overy PC

9th February 2022

Play Area, Gong Lane, Burnham Overy Staithe



An independent safety assessment of the playground and equipment by

David Bracey ILAM Dip.

David Bracey Play Safety Inspections

35 Chestnut Avenue, Lowestoft, Suffolk NR32 3JA

01502 217547 / 07500043756

Davidbracey2@tiscali.co.uk / www.playgroundinspections.weebly.co.uk



David Bracey has been inspecting playgrounds since 2004. Several thousands of sites have been successfully inspected. David has thirty years previous experience in Local Government working in Parks, Playground, Leisure and Environmental Management. He was a Play Inspector for Rospa between 2004 -11, and now concentrates working for his own company.

The company provide convenient and timely inspections undertaken by a Fully Independent Inspector, which guarantees a sensible approach and impartial report with no personal interest other than the safety of the facility. No links to any manufacturer or installer means a Fully Independent Inspection is given.

David Bracey is qualified to Rpii Annual Inspector Standard, which is the highest level. Has passed a Criminal Disclosure Check and holds Full Professional Indemnity and Public Liability Insurance.

The following forms an integral part of the inspection report

Reading it may save you unnecessary expenditure

- The equipment has been assessed, as relevant, in accordance with BS EN 1176: "Playground Equipment", BS EN 15312 (Sports Areas) and BS EN 14974 (Wheeled Sports)

The BS EN1176 was published on 1 January 1999 when existing standards were withdrawn. There are a number of areas where existing equipment may fail the standard. **This does not mean that equipment has suddenly become dangerous or that remedial action is required. Generally equipment that fails BS EN 1176 but passed the previous standard BS 5696 at time of installation should be considered safe (excluding any maintenance issues).**

Where there is a compliance failure, this is briefly noted and a risk assessment made of the failure. **Where we believe action is required this is indicated in more detail and identified as a medium or high risk.** (See paragraph 13). Where no action is indicated, in our opinion there is no practical economic action that can be taken and the risks do not justify removal of the item.

Low risk items should be monitored and if accidents occur, remedial action will be required (There is no such thing as NO risk).

Standard compliance is not mandatory or retrospective.
- The inspections cover:

 - Site safety
 - Suitability and conditions of ancillary items
 - Standard compliance, suitability and condition of equipment
 - Dimensional compliance, suitability and condition of surfacing

The report indicates the condition of the play area at the time of inspection. Subsequent events such as weather conditions, usage, or vandalism etc. may affect the condition of the play area. Routine inspections should be undertaken by the operator to monitor the effects of these.
- Standard assessment is undertaken where appraisal may be made without dismantling or destruction.
- The inspections are non-dismantling inspections. Where it is felt that removal of parts for assessment is required, this will be indicated. (See paragraph 13). It is not possible to check for internal corrosion/rot without dismantling the equipment.
- Surfacing has been assessed solely in terms of the area covered and its condition or security.

6. Where there is open water within easy walking distance of the play area it is recommended that a water safety report be commissioned (David Bracey Play Safety Inspections can undertake this).
7. Where there are trees within falling distance of the play area it is recommended that a report on the integrity of the tree is obtained from a competent arboricultural expert (see www.trees.org.uk for list of qualified consultants)
8. Where no protective surface is provided with items which have a fall height in excess of 600mm, the installation of a protective surface should be considered. Such surfacing is not mandatory but does represent good practice. It should be noted that BS EN 1176 and BS EN 1177 allow well-maintained grass for fall heights of up to 1500mm.
9. Surfacing up to a fall height of 600mm does not require testing for impact absorbency.
10. In addition to inspecting the equipment and surfacing, the inspection also looked at ancillary items and general design features where relevant to safety.
11. Wear to shackle pins and bushes on swings is difficult to detect on non-dismantling inspections. Checks are made to identify excessive movement in the 'D' shackle and where dry bearings are obvious. Whilst this action can often identify serious defects it does not preclude the possibility of shackle pin failure in rare circumstances. It is recommended that random inspection by removal of the 'D' shackle and pin is carried out as a regular maintenance feature in the site owner's work programme.
12. It should be noted that this is a safety report, not a standard compliance report, and compliance/non compliance with EN1176 is normally indicated. However failures may not be mentioned where they are very minor, or of a technical nature, and have no noticeable effect on safety.
13. A risk assessment of faults and Standard failures is given in terms of low, medium and high. **As a general principle items marked as "low" only require monitoring.** Items marked as "medium" require appropriate action within resources and individual site assessment. **Items marked as "high" require urgent action.** In rare cases where an item is likely to result in major injury or death, the operator or appropriate representative will be notified from the site by telephone. This will be indicated on the report.
14. There can be problems with assessing ground decay where synthetic surfaces have been installed. Similar problems may occur with sub-surface degradation. While care is taken to check ground decay and corrosion in supports, this cannot be done fully without removal and destruction of the surface.
15. In order to provide economic reports, standard wording is used for most common standard/maintenance failures. The inspector also works using previous year's reports (where available). **This may mean that where there have been few changes to the site, the current report may be similar to the previous year's report.**
16. The Disability Discrimination Act applies to play areas. There is a duty, where practicable, to make reasonable provision for equal opportunities for disabled people. David Bracey Play Safety Inspections can advise on this.
17. The Management of Health and Safety Regulations require a risk assessment of the play area for risks to users. This is a highly specialised subject. A risk assessment is included in

the report, although it is normally recommend that such formal risk assessments be undertaken every 4-5 years.



Inspection Scope for RPII Annual Inspectors

This document outlines the RPII scope for inspections undertaken by the Inspectors listed as Annual Inspectors on the RPII Register of Inspectors when undertaking Indoor Annual, Outdoor Annual, Outdoor Operational and Outdoor Routine inspections.

Inspections are undertaken with reference to the standards listed in this preamble only; where no date for the standard is given it will be the standard that is current at the time of inspection except where overlap periods are granted by the standards committee when standards are updated. The information contained in reports is provided to assist the owner/operator in fulfilling their responsibilities as detailed in the relevant standard. Other standards referenced within the listed standards do not form part of the inspection, unless they are also explicitly listed here.

The following standards are relevant to all installations of equipment that are publicly accessible to users; this includes public parks, pay and play parks, schools, nurseries, public houses, holiday parks, indoor play centres, farm parks etc. All equipment used or employed in publicly accessible areas should meet with the requirements of the relevant standards (listed below):

BS EN 1176 Parts 1, 2, 3, 4, 5, 6, 10 & 11 Playground equipment intended for permanent installation outdoors & indoors.

BS EN 1176 Part 7 - 'Guidance on Installation, Inspection, Maintenance and Operation' (this document gives guidance to the owners/operators of the facility on the installation, inspection, maintenance and operation of playground equipment, excluding ancillary items).

In the United Kingdom the National Foreword forms an important part to the understanding and implementation of the recommendations set out in this document. It clarifies the application of the document within the UK as best practice guidance, as the document has been used since its initial publication. Therefore, in the UK this standard (BS EN 1176 – Part 7) contains no requirements and needs to be read and implemented as guidance, with the use of the term 'shall' therefore becoming a recommendation, as in the term 'should'.

Domestic play equipment falls outside of the scope of BS EN 1176 and has its own standards (BS EN 71 series – Safety of Toys). Where domestic equipment can be identified this will be acknowledged in the report but any comments concerning compliance will follow the requirements and recommendations of BS EN 1176.

When water play items, including spray parks, are inspected any comments concerning compliance within the inspection will refer to EN 1176. We have not assessed these against the requirements of EN 17232 (Water play equipment and features).

Other equipment that is not clearly identified as unsupervised or domestic (natural play, self-build equipment etc.) will be assessed for compliance with the relevant standard listed below:

BS EN 15312 Free access multi-sports equipment

BS EN 14974 Skateparks

BS EN 16630 Permanently installed outdoor fitness equipment

BS EN 16899 Parkour equipment (plus RPII/API guidance notes)

Annual and Post Installation inspections will take into consideration compliance with these current standards, and defects related to wear and vandalism. Items not listed in the report have not been included in the inspection. The inspection will cover the playground equipment and the active area (that area which is obviously part of the playground), nominally up to three metres around, the fence line if closer, or other areas as agreed.

Operational inspections only take into consideration defects related to cleanliness, equipment ground clearances, ground surface finishes, exposed foundations, sharp edges, missing parts, excessive wear (of moving parts) structural integrity, wear and vandalism. Routine visual inspections relate only to the most obvious defects such as broken or missing parts, litter, vandalism and issues created by severe weather conditions (the intention is to identify hazards created by storm damage).

All inspections are non-dismantling, non-destructive and do not include any structural, toxicology or impact assessments defined in the standard; however, the inspector will undertake a manual test for stability and if equipment fails under manual load, or any other hazard is identified as an unacceptable risk, the owner/operator will be notified as soon as practicably possible.

The inspector will access all reasonably accessible equipment and will assess all reasonably accessible parts above the standing surface. Where it is not possible to access parts of the equipment without employing an alternative means of access the report will record the action required by the owner/operator to ensure the continued safe use of the equipment.

Ancillary equipment will be assessed using the inspector's knowledge and experience of the standards named in this document. (Note: Ancillary items are not included in the specific equipment-type parts of the EN 1176 series; hence they are not assessed for compliance with EN 1176 series and are subject to a general safety assessment).

The owner/operator is responsible for the overall safety of the equipment and area.

The inspector will not undertake any of the following works unless specifically agreed in writing at the time of order:

Checking the depth and underlying structural integrity of any surface areas and/or carrying out any testing of the impact attenuating properties of any surfaces; the identification of any corrosion, rot or other deterioration in any apparatus or equipment other than by an external inspection; the inspection of any equipment (or part thereof) that is beneath the playing surface (loose-fill materials may be moved to expose foundations); tightening any bolts, hinges or other fixing devices on any apparatus or equipment; assessing or inspecting any electrical installations contained on any site and/or apparatus and/or equipment; assessing or inspecting any water supplies and/or water features and/or any associated computerised systems

(including carrying out any programming); where planting or trees are mentioned in the report no assessments of toxicity, suitability or condition are undertaken – the owner/operator should have suitable inspections provided by a competent person.

The owner/operator should have a 'design risk assessment' provided by the manufacturer/designer of the area for the equipment and location in which the facility is installed.

The operator is responsible for managing risks of their provision and is required by law to carry out a 'suitable and sufficient assessment' of the risks associated with a site or activity. This inspection shall be considered as contributing to the operator's discharge of this responsibility.

The details contained within the report are a snapshot of the condition at the time of inspection only and subsequent events may affect the condition of the facility. Suggested remedial actions are based on the knowledge and experience of the inspector and/or that of the inspection company. The owner/operator should always seek the advice of the manufacturer or a competent person when undertaking repairs and/or modifications to equipment.

Table 1

The operator is responsible for following the guidance of the relevant standards. The standards give guidance on the installation, inspection, maintenance and operation of the various types of facilities. The inspection guidance is listed in Table 1, with an indication of which parts will be included in an RPII Annual or Post-Installation Inspection. The relevant standards also contain additional parts which the operator should follow.

Inspection Recommendations of relevant standards Refer to relevant standards for full text	Annual Main	RPII Annual/ Post Installation Inspection
6.1 d) Overall levels of safety of equipment (see note 1)	✓	[1] ✓
6.1 d) Overall levels of safety of foundations (see note 1)	✓	✓[1]
6.1 d) Overall levels of safety of playing surfaces (see note 2)	✓	✓[2]
6.1 d) Compliance with the relevant parts of the standard and or risk assessment (see note 3)	✓	✓[3]
6.1 d) Effects of weather	✓	✓
6.1 d) Presence of rot, decay or corrosion (see note 1)	✓	✓[1]
6.1 d) Assessment of repairs made or added or replaced components (see note 4)	✓	✓[4]
6.1 d) Excavation or dismantling/additional measures	✓	✗
6.2.1 Assessment of glass reinforced plastics (see note 5)	✓	✓[5]

6.2.1 Inspection of one post equipment (see note 1)	✓	✓[1]
6.2.4 Undertaking the Operators inspection protocol	✓	✗

NB: The clause numbers in table 1 are taken from BS EN 1176 - Part 7:2020. The content is equally applicable to all other relevant standards listed herein. Playgrounds contain a range of equipment from different manufacturers and installed over a number of years; operators should implement any guidance provided by the manufacturer. Item specific detail is not readily available to RPII Playground Inspectors, whose report contributes to the operator's overall Annual Main Inspection as detailed in the relevant

[1] A manual test only is undertaken for stability. Wear and instability are only detectable where readily apparent without dismantling or destruction and without the use of tools, excavation or specialist equipment. Rot and corrosion are tested or with a hammer and/or steel rod. Decay in timber may exist which can only be found with specialist equipment.

[2] Only the visible condition and dimensional compliance of surface extent is considered. Neither testing of impact attenuating properties nor measurement of the thickness of bound surfaces are undertaken on RPII annual inspections.

[3] The inspection assesses compliance where this can be tested on site using manual methods without dismantling, destruction and without the use of tools or specialist equipment.

[4] The operator should use manufacturer's recommended parts, or equivalent. We are unable to verify if such parts have been used, and any subsequent change in quality or performance.

[5] Visible glass fibres will be noted in reports. The operator is responsible for repairs or replacement.

Name of site: Play Area, Gong Lane, Burnham Overy Staithe

Client: Burnham Overy PC

Date: 9th February 2022

Inspector: David Bracey

Site Comments

Annual inspection of well equipped play area. The play area is in good condition and appears to be well maintained. Maintenance is required as noted in report.

Site and Ancillary Items

The following items have been inspected and found to be in good order:

Access

Timber Shelter



Timber Picnic Bench



Cleanliness

Minimum Space – equipment

Traffic Clashes - users

Signs – Road signs, Ownership, ‘Dogs must be kept on a lead - no fouling’, No Kite Flying etc.







Electric Cables on perimeter – ‘No Kite Flying’ and ‘Danger of Death’ signs in place.

Work is required on the following:

Self Closer Gate x 1 - Entrapment on the side(s) of gate. Recommend to adjust gate/post/fit new rubber buffer to ensure a spacing of at least 12mm throughout the range of the gate to remove the finger entrapment. The 12mm gap should also apply on the hinge side of the gate – Low to Medium risk.



Mature trees in play area – Recommend to inspect annually by a qualified arboriculturist and to remove any dead, diseased and damaged wood.

Seats x 3 – Recommend clean off algae and cut back planting – Low risk.



General surface -Grass – Molehills form trip hazards - Recommend to remove moles or level off molehills to eliminate trip hazards – Low risk.



PLAY EQUIPMENT:

Item: Small Goals x 2



EN 748 Compliance

The item fails to meet the requirements of EN748 in the following respects:

Bolt exposed - Recommend cut off and file down excess threads to bolts at back supports to eliminate hazards if users swing/grab bars – Low risk.





Goals move in sockets – finger entrapment possible – Recommend wedge - Low risk.



Repair / Maintenance recommended

Recommend repair damaged nets – Low risk.



Surfacing: Grass

EN748 Compliance

The surface meets the dimensional requirements of EN748.

Repair / Maintenance recommended

The surfacing is in a satisfactory condition and no work is required at this time.

Item: Cable Runway - Kompan



EN 1176 Compliance

The item meets the requirements of the item meets the requirements of EN1176 where this may be tested on site without dismantling or destruction.

N.B. The seat revolves, but it is recommended to accept this design by Kompan as EN1176 states 'seats should be designed so that the user can leave the cableway quickly and at all times', the inspector would take a view that in certain instances the revolving seat would actually ensure that the user would grip the hand suspension tighter. It is however recommended to monitor for any reports of accidents due to the revolving seat and bring to the attention of the manufacturer and/or replace with non revolving seat.



Repair / Maintenance recommended

No remedial maintenance is required at this time.

Surfacing: Safety Matting

EN 1176 Compliance

The surface meets the dimensional requirements of EN1176.

Repair / Maintenance recommended

Recommend infill and level uneven areas in surface to eliminate trip hazards - Low to Medium risk.



Item: Basket Swing - Europlay



EN 1176 Compliance

The item meets the requirements of EN1176 where this may be tested on site without dismantling or destruction.

Repair / Maintenance recommended

No remedial maintenance is required at this time.

Surfacing: Safety Matting

EN 1176 Compliance

The surfacing meets the dimensional requirements of EN1176.

Repair / Maintenance recommended

The surfacing is in a satisfactory condition and no work is required at this time.

Item: Static Mushrooms x 3



EN 1176 Compliance

The item meets the requirements of the item meets the requirements of EN1176 where this may be tested on site without dismantling or destruction.

Repair / Maintenance recommended

Recommend monitor slight damage to one item – Low risk.



Surfacing: Grass

EN 1176 Compliance

The surface meets the dimensional requirements of EN1176.

Suitably well maintained grass and topsoil, with at least 150mm of soil beneath, is acceptable to EN1176 for items with a fall height of up to 1500mm subject to a risk assessment.

Repair / Maintenance recommended

The surfacing is in satisfactory condition and no work is required at this time.

Item: 'Simply Play' Multiplay - Kompan



EN 1176 Compliance

The item meets the requirements of the item meets the requirements of EN1176 where this may be tested on site without dismantling or destruction.

Repair / Maintenance recommended

No remedial maintenance is required at this time.

Surfacing: Matting

EN 1176 Compliance

The surface meets the dimensional requirements of EN1176.

Repair / Maintenance recommended

This type of safety surface should have grass present to provide adequate protection in user falls, as the grass roots absorb the impact of any falls. The surface therefore does not give the same protection as with grass and the risk of damage to users in falls is increased. In the first instance it is recommended to spread seed and soil mix over the worn area – Low to Medium risk.



Item: Type 1 Rocker - Seesaw - Kompan



EN 1176 Compliance

The item meets the requirements of the item meets the requirements of EN1176 where this may be tested on site without dismantling or destruction.

Repair / Maintenance recommended

No remedial maintenance is required at this time.

Surfacing: Matting/Grass

EN 1176 Compliance

The surface meets the dimensional requirements of EN1176.

Repair / Maintenance recommended

The surfacing is in a satisfactory condition and no work is required at this time.

Item: 1 Bay 2 Cradle Seat Swing (2200mm) – Wicksteed Leisure



En1176 Compliance

The item meets the requirements of EN1176 where this may be tested on site without dismantling or destruction.

Repair/ Maintenance recommended

No remedial maintenance is required at this time.

Surfacing: Tiles/Matting

EN 1176 Compliance

The surfacing meets the dimensional requirements of EN 1176.

Repair/ Maintenance recommended

Recommend re-glue and fill gaps and joints (wet pour kits are available) and where surface is lifting and gaps appearing. Leaving the gaps may cause trip hazards and allow weeds to grow and push up the surface further – Recommend firstly to remove weeds and moss - Low risk.



Item: 1 Bay 2 Flat Seat Swing (3100mm) – Wicksteed Leisure



En1176 Compliance

The item meets the requirements of EN1176 where this may be tested on site without dismantling or destruction.

Repair/ Maintenance recommended

No remedial maintenance is required at this time.

Surfacing: Tiles/Matting

EN 1176 Compliance

The surfacing meets the dimensional requirements of EN 1176.

Repair/ Maintenance recommended

Algae growth on surface which may be slippery when wet.
Powerwashing or brushing with a stiff broom is recommended. Care should be taken to ensure that the surface can sustain high pressure washing – Low Risk.



Trip zones found at edge of surface – Recommend build up ground levels to remove trip hazard – Low to Medium risk.



Item: Mound Slide - Hurst



EN 1176 Compliance

The item fails to meet the requirements of EN1176 in the following respects:

Barriers not infilled – Recommend monitor - Low risk.



Insufficient height on barriers - Recommend monitor - Low risk.



The step access fails entrapment requirements (at steps – distance should not be between 89 and 230mm) – Recommend monitor – Low risk.



Repair / Maintenance recommended

No remedial maintenance work is required at this time.

Surfacing: Grass

EN 1176 Compliance

The surfacing meets the dimensional requirements of EN1176.

Suitably well maintained grass and topsoil underneath, with at least 150mm of soil beneath is acceptable to EN1176 for items with a fall height of up to 1500mm subject to a risk assessment.

Repair / Maintenance recommended

The surfacing is in a satisfactory condition and no work is required at this time.

Item: Roundabout - Hussan



EN 1176 Compliance

The item meets the requirements of the item meets the requirements of EN1176 where this may be tested on site without dismantling or destruction.

Repair / Maintenance recommended

No remedial maintenance is required at this time.

Surfacing: Safety Matting

EN 1176 Compliance

The surface meets the dimensional requirements of EN1176.

Repair / Maintenance recommended

The surfacing is in a satisfactory condition and no work is required at this time.

Item: Half Pipe - Bat Ramps



EN 14974 Compliance

The item fails to meet the requirements of EN14974 in the following respects:

Barriers should be 1200mm high (currently 1100mm) - Recommend monitor only – Low risk.



Gap between platform and lower edge of barrier should be 60mm (currently 100mm) – Recommend monitor only - Low risk.



Repair / Maintenance recommended

Recommend remove rough and damaged edges to eliminate riding and falling hazard – Medium risk.



Surfacing: Concrete

EN 1176 Compliance

The surface meets the dimensional requirements of EN14974.

Repair / Maintenance recommended

The surfacing is in a satisfactory condition and no work is required at this time.

Item: Play Bus – Action Play and Leisure



EN 1176 Compliance

The item meets the requirements of the item meets the requirements of EN1176 where this may be tested on site without dismantling or destruction.

Repair / Maintenance recommended

No remedial maintenance is required at this time.

Surfacing: Matting

EN 1176 Compliance

The surface meets the dimensional requirements of EN1176.

Repair / Maintenance recommended

The surfacing is in a satisfactory condition and no work is required at this time.

Item: Trim Trail comprising:

Step Posts with Springy Plank



EN 1176 Compliance

The item meets the requirements of the item meets the requirements of EN1176 where this may be tested on site without dismantling or destruction.

Repair / Maintenance recommended

No remedial maintenance is required at this time.

Surfacing: Grass

EN 1176 Compliance

The surface meets the dimensional requirements of EN1176.

Suitably well maintained grass and topsoil, with at least 150mm of soil beneath, is acceptable to EN1176 for items with a fall height of up to 1500mm subject to a risk assessment.

Repair / Maintenance recommended

The surfacing is in a satisfactory condition and no work is required at this time.

Item: Swinging Log Traverse with Tram Trax



EN 1176 Compliance

The item meets the requirements of the item meets the requirements of EN1176 where this may be tested on site without dismantling or destruction.

Repair / Maintenance recommended

No remedial maintenance is required at this time.

Surfacing: Grass

EN 1176 Compliance

The surface meets the dimensional requirements of EN1176.

Suitably well maintained grass and topsoil, with at least 150mm of soil beneath, is acceptable to EN1176 for items with a fall height of up to 1500mm subject to a risk assessment.

Repair / Maintenance recommended

The surfacing is in a satisfactory condition and no work is required at this time.

Item: Gym Rings with Beam and Step Posts – Action Play and Leisure



EN 1176 Compliance

The item meets the requirements of the item meets the requirements of EN1176 where this may be tested on site without dismantling or destruction.

Repair / Maintenance recommended

Recommend replace damaged / missing caps x 5 – Low risk.





Surfacing: Matting

EN 1176 Compliance

Insufficient protective surfacing has been provided – should be 1700mm either side of rings (currently 1380mm) and same distance at each end from the end rings - Recommend add required matting – Low risk.



Repair / Maintenance recommended

Recommend infill hole to eliminate trip hazard (on south side of grass surface one metre from item) - Low to Medium risk



Item: Ladder with Step Post



EN 1176 Compliance

The item meets the requirements of the item meets the requirements of EN1176 where this may be tested on site without dismantling or destruction.

Repair / Maintenance recommended

No remedial maintenance is required at this time.

Surfacing: Grass

EN 1176 Compliance

The surface meets the dimensional requirements of EN1176.

Suitably well maintained grass and topsoil, with at least 150mm of soil beneath, is acceptable to EN1176 for items with a fall height of up to 1500mm subject to a risk assessment.

Repair / Maintenance recommended

The surfacing is in satisfactory condition and no work is required at this time.

Item: Slatted Bridge with Step Post



EN 1176 Compliance

The item meets the requirements of the item meets the requirements of EN1176 where this may be tested on site without dismantling or destruction.

Repair / Maintenance recommended

No remedial maintenance is required at this time.

Surfacing: Grass

EN 1176 Compliance

The surface meets the dimensional requirements of EN1176.

Suitably well maintained grass and topsoil, with at least 150mm of soil beneath, is acceptable to EN1176 for items with a fall height of up to 1500mm subject to a risk assessment.

Repair / Maintenance recommended

The surfacing is in a satisfactory condition and no work is required at this time.

Item: Kickwall - Lappsett



EN 1176 Compliance

The item meets the requirements of the item meets the requirements of EN1176 where this may be tested on site without dismantling or destruction.

Repair / Maintenance recommended

Recommend replace (or tape over) damaged cap – Low risk.



Surfacing: Grass

EN 1176 Compliance

The surface meets the dimensional requirements of EN1176.

Suitably well maintained grass and topsoil, with at least 150mm of soil beneath, is acceptable to EN1176 for items with a fall height of up to 1500mm subject to a risk assessment.

Repair / Maintenance recommended

The surfacing is in a satisfactory condition and no work is required at this time.

Item: Basket Ball Post with Training Net - Adidas



EN 15312 Compliance

The item meets the requirement of EN15312 where this may be tested on site without dismantling or destruction.

Repair / Maintenance recommended

No remedial maintenance is required at this time.

Surfacing: Bitmac

EN 1176 Compliance

The surface meets the dimensional requirements of EN15312.

Repair / Maintenance recommended

Algae growth on surface which may be slippery when wet. Power washing or brushing with a stiff broom is recommended on safety surfaces, care should be taken to ensure that the surface can sustain high pressure washing – Low risk.



Item: Table Tennis



EN 15312 Compliance

The item meets the requirements of EN15312 where this may be tested on site without dismantling or destruction.

Table has been moved off the Bitmac area used by the Basketball. It is Recommended to monitor if any conflict exists between users, if so the table may need to be moved further away.

Repair / Maintenance recommended

No remedial maintenance is required at this time.

Surfacing: Grass

EN 1176 Compliance

The surface meets the dimensional requirements of EN15312.

Repair / Maintenance recommended

Recommend infill hole (rabbit scrape) nearby to eliminate trip hazard - Low to Medium risk.



Risk Assessment Evaluation

Client: Burnham Overy PC

Site: Play Area, Gong Lane, Burnham Overy Staithe

Date: 9th February 2022

Type: Age 3 – 15 years

Risk Score	Risk Categories
1 -3	Very Low Risk -Monitor
4 -7	Low Risk – Monitor and take reasonable action if possible
8 - 12	Medium Risk – Take action to reduce if possible, or available
13 - 20	High Risk – Take Action immediately and access control measures
21 +	Unacceptable Risk – Remove or immobilise before taking immediate action and assessment of control measures

Ancillary Items and Environmental or Other Hazards

Ancillary Items	Risk Score	Comments	Action or Control
General Surface - Grass	7		See Report
Signs	3		Monitor
Seats	5		See Report
Gate	6		See Report
Shelter	4		Monitor
Picnic Bench	3		Monitor
Access	3		Monitor

Environmental Hazards	Risk Score	Action, Comment or Control Recommended
Free/Fall Space	2	Monitor
Traffic Clashes	3	Monitor
Design Defects	3	Monitor

Equipment and Surfacing

Equipment Items	Surface	Risk Score	Action, Control or Comments
Seesaw	Matting/Grass	3	Monitor
Multiplay	Matting	7	See Report
Small Goals	Grass	6	See Report
Basket Swing	Matting	5	Monitor
Mushrooms x 3	Grass	5	See Report
1 Bay Cradle Seat Swing	Tiles/Matting	5	See Report
1 Bay 2 Flat Seat Swing	Tiles/Matting	6	See Report
Mound Slide	Grass	7	See Report
Roundabout	Matting	3	Monitor
Half Pipe	Concrete	8	See Report
Play Bus	Matting/Grass	4	Monitor
Step Posts with Springy Plank	Grass	3	Monitor
Swinging Logs with Tram Tax	Grass	3	Monitor
Gym Rings with Beam	Matting	7	See Report
Ladder	Grass	3	Monitor
Slatted Bridge	Grass	3	Monitor
Kickwall	Grass	6	See Report
Basket Ball Post/Training Net	Bitmac	5	See Report
Table Tennis	Grass	7	See Report

Risk assessment evaluation should be read in conjunction with Annual or Post Installation reports. Where action or control relates to maintenance, non-compliance or minor defects read Annual Inspection or Post Installation reports for detailed comments. Serious or high risk failures should, however be noted. Failure to comply with the standards will be identified in the reports.

Design, location and physical site factors may determine the overall risk of the site. These may be difficult to change economically, However, where maintenance or control methods are undertaken the site could be reduced to **Low** Risk subject to a future inspection and reassessment.

ASSESSED LEVEL OF RISK FOR THE PLAYGROUND AT THE TIME OF INSPECTION WAS MEDIUM RISK